USTER® TENSORAPID 5

The strength measurement system

Technical Data

February 2020





Tensile testing and analyzing instrument for the yarn quality assurance of a wide variety of yarns and fabrics.

Elements

of the USTER® TENSORAPID 5 installation



Accessories

Options

Basic installation

Overall Installation	Functions	 Measurement of tensile strength and elongation of an extensive range of yarns and fabrics Analysis, evaluation and storage of measurement values Automatic check of all measured values Automatic comparison with the benchmarking tool USTER® <i>STATISTICS</i> Editor for customizing reports and setting of mill limits Smart view focusing on exception and outliers Filter functions for quick data selection and for the preparation of long-term reports
	Included in the delivery	 Test unit Control unit Touchscreen Printer Application software Table Calibration device ISOINSPECT

Subsystem of the USTER® TENSORAPID 5 basic version:

Test unit (1)	Instrument type 500 N	 0.01 to 500 N Recommended for staple fiber yarns Configuration: Clamping device 500 N with finger tensioner or Clamping device 500 N with unwinding device for the transportation of the yarn between the individual tests
	Instrument type 1 500 N	 0.05 to 1500 N Recommended for staple fiber yarns, skein and fabric tests Configuration: Clamping device 1500 N with finger tensioner or Clamping device 1500 N with unwinding device for the transportation of the yarn between the individual tests
	Measuring principle	Constant rate of extension CRE
	Testing method	Simple tensile test, single yarn testing
	Force measuring arrangement	Practically inertialess electronic force measurement

USTER® *TENSORAPID 5* The strength measurement system

Test unit (1)	Elongation measuring arrangement	 Electronic elongation measurement Measuring accuracy for force and elongation measurement: for force ±1% (above 100 cN) or ±1 cN (below 100 cN), and for elongation ±1% 	
	Clamp speed	Continuously adjustable between 50 and 5000 mm/min	
	Pre-tension	Adjustable between 0.5 and 6000 cN	
	Test lengths	 With horizontal position of clamps: continuously adjustable between 200 and 1000 mm With vertical position of clamps: continuously adjustable between 100 and 1000 mm 	
	Elongation measuring range	 For 100 mm test length: 0 to 1000% For 200 mm test length: 0 to 500% For 500 mm test length: 0 to 140% 	
	Yarn changer	 Automatic changing of the yarn preparation unit into the clamps Setup of 40 samples, run automatically even when a within fail Later continuation of the incomplete test 	
	Yarn clamps	Pneumatically actuated yarn clamps with exchangeable clamp inserts of various materials, and exchangeable reduction curves (see options); the clamp pressure is programmable in stages	
Control unit (2)	Computer software	 USTER[®] TENSORAPID 5 intuitive touch application software Windows Embedded 8.1 operating system System pre-configured and locked down Simple full system update process 	
	Computer hardware	 Industrial computer with Intel processor 3 internal hard drives for data security and system redundancy 1 TB test data storage 	
	Computer accessories	 Large easy to read touchscreen monitor Laser printer 	

Options

Reduction clamps (11)	Application range	 High strength filament yarns and ply yarns Undrawn, partially drawn or very fine filament yarns Test materials with a tendency to stick to polished surfaces Filament yarns with abrasive additives for obtaining matt surfaces (e.g. titanium dioxide)
Clamps for fabric tests (10)	Application range	 Testing of woven fabric strips according to DIN 53857 (50 mm width) Testing of fiber assemblies for the adhesion test
Unwinding device (7)	Application range	Allows quick sample control of whole bobbins due to unwinding of long yarn pieces between the measurements with winding speeds up to 400 m/min
Clamps for skein tests (9)	Application range	Clamps for the testing of the skeins (hank test) according to ASTM standard D 1578
Vibration suppressor (12)	Application	For measurements of material with a breaking force less than 200 cN, or if vibrations of the floor are to be expected
Accessories (5)	Tools	 For the exchange of the clamps (e.g. from clamps for fabric strips to clamps for skein test to clamps for high resistance yarns with 180° force reduction curve) For the exchange of the clamp inserts For the exchange of the reduction curve
	Clamp inserts	To enable the appropriate testing of various types of materials, different clamp inserts are included in the delivered parts
Package carrier (13)	Application	Package truck for creeling and transporting of up to 24 yarn packages (with separate extension set for up to 40 yarn packages)
	Package dimensions	 With 24 packages: max. ø125 mm; length max. 450 mm With 40 packages: max. ø 60 mm; length max. 450 mm

Application software

Reports	Type of report	 Standard test report of the measurement series USTER® Quality Report (summary of the key data and the test results on one page; quality certificate) Pre-defined table reports and graphical reports for different application Long-term reports Customized reports
Display and printout of the reports	Display and printout of the reports	Live view report during the measurement – Analysis tool with all measured data and graphical output – Smart view report for exceptions and outliers – Automatic printout possibility after the measurement
	Limit values Setting of customized standard deviation, re – Automatic verificatio – Measured values wh marked with red or	 Setting of customized limits according to the USTER® STATISTCS, standard deviation, relative and absolute values Automatic verification of the measured value Measured values which exceed the limit will be marked with red or purple color in the report
Numerical results Time to break Breaking force Breaking elongation Tenacity Breaking work Part work done Reference values Modulus values Modulus values	Time to break	Time from the start of measurement to the break of the sample
	Breaking force	Maximum force value measured during the tensile test
	Breaking elongation	Elongation at maximum breaking force value
	Tenacity	Breaking force in relation to the yarn count of the sample
	Breaking work	Work done to break (enclosed area below the force/elongation characteristic curve up to the point of breaking force)
	Part work done	Partial work done to break (enclosed area below the force/elongation characteristic curve and two freely-selected elongation values)
	Reference values	A maximum of any 10 points on the force/elongation characteristic curve (choice of force or elongation)
	Modulus values	A maximum of 10 modulus values at any point on the force/elongation characteristic curve

Statistics	Statistical values	 Mean value Standard deviation s Coefficient of variation CV Q95% confidence interval USP™ (USTER® <i>STATISTICS</i> Percentile) Minimum value Maximum value 	
	USTER® <i>STATISTICS</i>	 Comparison of measured values with the USTER® STATISTICS Material-dependent USTER® STATISTICS are stored in the data-base Setting of limit values based on the USTER® STATISTICS 	
Graphic output of results	Stroke diagram	Available for breaking force and elongation or tenacity and elongation	
	Diagram	Available for force and elongation or for other results configurable	
	Force/ elongation diagram	 Show all single measurements in curves Easier detection of the sample due to different colors 	
	Modulus/ elongation diagram	Modulus curves of all single measurements	
	Spectrogram	 Available for force and elongation Pre-condition: needs 200 within tests per sample 	
Data protection	Backup	Automatic backup to dedicated internal hard drive every 15 minutes	
Input of data, output of results, languages, units	Dialog and report languages	English, German, French, Italian, Spanish, Portuguese, Turkish, Russian, Chinese or Japanese can be selected (other languages on request)	
	Possible units	 Force values: N, cN, kgf, gf, lbf, ozf Yarn count: ktex, tex, dtex, denier, Nm, Nec, Nel, New, grn/yd, Y.S.W. Tenacity: mN/tex, cN/tex, gf/denier, Rkm, CSP, MPA 	
System security	Protection function	 System protected from viruses, network and other security threads Remote support capabilities built in Diagnostic tools with extensive event logging Automated system recovery 	

General

General ambient conditions	Room climate	The ambient conditions must be maintained in order to avoid any influencing of the test material according to ISO 139 (2015) – Humidity: 65±4% – Temperature: 20±2° Standard atmosphere
Installation data	Electrical connection	Single-phase mains with protective conductor
	Nominal voltages	100 to 240 VAC
	Mains frequency	50/60 Hz
	Power consumption	Maxiumum 1000 VA
	Compressed air connection	 Air quality: according to ISO 8573.1, class 3 Min. pressure at inlet of air filter regulator: 6 bar Max. pressure at inlet of air filter regulator: 7 bar
	Compressed air consumption	18 m ³ /h with normal pressure Noise level at blowing jet: max. 80 dB(A) at 1m distance and according to the type of yarn
Weight of the installation	Tester	260 kg
	Table	83 kg

Uninterrupted power supply (UPS)

	UPS must be provided by the customer	
	UPS Model	Tower
	UPS Bypass Type	ON-Line
Electrical Input	Nominal Voltage	120 VAC, 220-240 VAC
	Voltage range 120 VAC	90–138 VAC
	Voltage range 230 VAC	160–276 VAC
	Frequency	50/60Hz
Output	Nominal Output Voltage	120 VAC, 230 VAC
	Power Capacity	1500 VA (1.5 kVA)/1350 W
	Voltage regulation	+/-3 %
Enviroment	Safety markings 120/208 V	UL, CUL, VCCI
	Safety markings 230 V	CE, GS
	Ambient operating temp.	Laboratory condition are acceptable
	Relative humidity	Laboratory condition are acceptable

Note: It is not permitted to connect a Laser Printer.



Space required for the USTER® TENSORAPID 5



Uster Technologies has made all possible efforts to ensure that all information is accurate at the time of publication. Hereby it is declared that alterations to the product may be possible at any time. In these cases the information contained in this technical datasheet is subject to change without notice.



Uster Technologies AG

Sonnenbergstrasse 10 8610 Uster Switzerland T. +41 43 366 36 36 F. +41 43 366 36 37 sales@uster.com www.uster.com